

HISTORIC RESOURCES INVENTORY

(State use only) Ser _____ Site 11/515500/695200 Mo. _____ Yr. _____
 UTM _____ Q _____ NR IV SHL _____
 Lat _____ Lon _____ Era _____ Sig _____
 Adm _____ T2 _____ T3 _____ Cat _____ HABS _____ HAER _____ Fed _____
HP 41 D.2

IDENTIFICATION

1. Common name: Collins House *LORHR*
2. Historic name, if known: Collins House
3. Street or rural address 1107 'R' Street
 City: Fresno, California ZIP: 93721 County: Fresno
4. Present owner, if known: David C. Gauvin Address: 1107 'R' Street
 City: Fresno, California ZIP: 93721 Ownership is: Public Private
5. Present Use: Residence Original Use: Residence
 Other past uses: _____



DESCRIPTION

6. Briefly describe the present physical appearance of the site or structure and describe any major alterations from its original condition:

Well kept and largely refinished stick framed two story wood house. Cross gabled roof with eastlake decoration at eaves. Ionic capiteled columns on porch. Bay window on south frontage engages the porch which turns the corner and provides a complete first floor cover on the 'R' Street frontage. Raised off of ground approximately 44" horizontal shiplap siding throughout. Natural oak front door. Original wood shingles covered by asphalt shingles.

Remodeled by Gauvin as professional office space!

7. Locational sketch map (draw and label site and surrounding streets, roads, and prominent landmarks):



8. Approximate property size:
 Lot size (in feet) Frontage 150'
 Depth 150';
 or approx. acreage 0.52.
9. Condition: (check one)
 a. Excellent b. Good c. Fair
 d. Deteriorated e. No longer in existence
10. Is the feature a. Altered? b. Unaltered?
11. Surroundings: (Check more than one if necessary)
 a. Open land b. Scattered buildings
 c. Densely built-up d. Residential
 e. Commercial f. Industrial
 g. Other Church
12. Threats to site:
 a. None known b. Private development
 c. Zoning d. Public Works project
 e. Vandalism f. Other
13. Date(s) of enclosed photograph(s): 1978

16 lot split

NOTE: The following (Items 14-19) are for structures only.

14. Primary exterior building material: a. Stone b. Brick c. Stucco d. Adobe e. Wood
f. Other _____
15. Is the structure: a. On its original site? b. Moved? c. Unknown?
16. Year of initial construction 1905 This date is: a. Factual b. Estimated
17. Architect (if known): Unknown- probably none
18. Builder (if known.): Dave Cowan
19. Related features: a. Barn b. Carriage house c. Outhouse d. Shed(s) e. Formal garden(s)
f. Windmill g. Watertower/tankhouse h. Other _____ i. None

SIGNIFICANCE

20. Briefly state historical and/or architectural importance (include dates, events, and persons associated with the site when known):

A nice structure, well preserved, and a part of a larger historic area. "Victorian" style in massing with numerous individual details. Mr. Collins was elected to California Assembly and served as Sheriff for 8 years. Dr. Clinton Collins, his son lived in the house for many years. He served as president of the County Medical Society and was president of the Community Hospital Staff. Another son, William Collins, served as a Fresno County Supervisor for 28 years.

21. Main theme of the historic resource: (Check only one): a. Architecture b. Arts & Leisure
c. Economic/Industrial d. Exploration/Settlement e. Government f. Military
g. Religion h. Social/Education

22. Sources: List books, documents, surveys, personal interviews, and their dates:

23. Date form prepared: 6/22/78 By (name): William E. Patnaude
Address: 1050 'S' Street City Fresno, California ZIP: 93721
Phone: (209) 486-8150 Organization: Allen Y. Lew & William E. Patnaude, Inc.

(State Use Only)