

ATTACHMENTS

EXHIBIT A:

HISTORIC RESOURCES INVENTORY

(State use only)

Ser 11/516250/6 Site 00 Mo. NR Yr. 3
UTM Q SHL 3
Lat Lon Era Sig
Adm T2 T3 Cat HABS HAER Fed
HP. 86 D. 3

IDENTIFICATION


- Common name: St. John's Cathedral
- Historic name, if known: Same
- Street or rural address 2814 Mariposa Street
City: Fresno, California ZIP: 93721 County: Fresno
- Present owner, if known: Roman Catholic Bishop of Fresno Address: 2814 Mariposa Street
City: Fresno, California ZIP: 93721 Ownership is: Public ☐ Private ☒
- Present Use: Roman Catholic Cathedral Original Use: Same
Other past uses: None

DESCRIPTION

- Briefly describe the present physical appearance of the site or structure and describe any major alterations from its original condition:

Large red brick structure in typical early-christian church plan; ie nave with side aisles, small transept, apse, narthex and twin towers at entry elevation. Tri-partite entry. Gothic arched windows and doors but round arch openings in bell towers. Small rose window on west end. All windows filled with stained glass. Aluminum colored spires. Ornate interior. One building in a complex of 3. Buttressing of corners and walls handled very simply as are most of the details.

- Locational sketch map (draw and label site and surrounding streets, roads, and prominent landmarks):



- Approximate property size:

Lot size (in feet) Frontage 150
Depth 175;
or approx. acreage 0.60.

- Condition: (check one)

a. Excellent ☐ b. Good ☒ c. Fair ☐
d. Deteriorated ☐ e. No longer in existence ☐

- Is the feature a. Altered? ☐ b. Unaltered? ☐

- Surroundings: (Check more than one if necessary)

a. Open land ☐ b. Scattered buildings ☐
c. Densely built-up ☐ d. Residential ☒
e. Commercial ☒ f. Industrial ☐
g. Other ☐

- Threats to site:

a. None known ☒ b. Private development ☐
c. Zoning ☐ d. Public Works project ☐
e. Vandalism ☐ f. Other ☐

- Date(s) of enclosed photograph(s): 1978

NOTE: The following (Items 14-19) are structures only.

14. Primary exterior building material: a. Stone ☐ b. Brick ☒ c. Stucco ☐ d. Adobe ☐ e. Wood ☐
f. Other ☐
15. Is the structure: a. On its original site? ☒ b. Moved? ☐ c. Unknown? ☐
16. Year of initial construction 1902 This date is: a. Factual ☒ b. Estimated ☐
17. Architect (if known): T.M. Bermingham
18. Builder (if known): J.E. Birmingham and F.J. Williams
19. Related features: a. Barn ☐ b. Carriage house ☐ c. Outhouse ☐ d. Shed(s) ☐ e. Formal garden(s) ☐
f. Windmill ☐ g. Watertower/tankhouse ☐ h. Other ☐ i. None ☒

SIGNIFICANCE

20. Briefly state historical and/or architectural importance (include dates, events, and persons associated with the site when known):

Very important Catholic Church. The oldest remaining Catholic Church in the City. Built outside the City originally but soon became a nucleus for a fine residential area of the city. A religious and social center for over 75 years and an important part of the social and physical fabric of the city.



21. Main theme of the historic resource: (Check only one): a. Architecture ☐ b. Arts & Leisure ☐
c. Economic/Industrial ☐ d. Exploration/Settlement ☐ e. Government ☐ f. Military ☐
g. Religion ☒ h. Social/Education ☐

22. Sources: List books, documents, surveys, personal interviews, and their dates:

23. Date form prepared: 6/24/78 By (name): William E. Patnaude
Address: 1050 'S' Street City Fresno, California ZIP: 93721
Phone: (209) 486-8150 Organization: Allen Y. Lew & William E. Patnaude, Inc.

(State Use Only)

as
"Local Historic
Monument"



C-P

FH/R Prof Ser. 5
Other Rel. Spec

13-407 a-1,2
D-1,2,3
C-1,2,4

Zone Map 4C

EXHIBIT B:

HISTORIC RESOURCES INVENTORY

(State use only)

Ser 117516400/6 Site 50 Mo. Yr.
UTM Q NR 4 SHL
Lat Lon Era Sig
Adm HP87 T2 T3 Cat HABS HAER Fed

IDENTIFICATION


- Common name: St. John's Residence *or Rectory*
- Historic name, if known: Same
- Street or rural address: 2814 Mariposa
City: Fresno ZIP: 93721 County: Fresno
Roman Catholic Bishop of Fresno
- Present owner, if known: c/o ST. JOHN'S CATHEDRAL Address: 2814 Mariposa
City: Fresno ZIP: 93721 Ownership is: Public ☐ Private ☒
- Present Use: Rectory Original Use: Same
Other past uses: None

DESCRIPTION

- Briefly describe the present physical appearance of the site or structure and describe any major alterations from its original condition:

Three story red brick building. One of 3 in the cathedral complex. Red barrel tile fascia at parapet on Mariposa frontage. All decorative items limited to Mariposa Street frontage. All other facades plain brick walls with double hung windows. Two story portico with brick columns and applied decoration at first floor, and top of third floor. Building is in good condition - well maintained.

- Locational sketch map (draw and label site and surrounding streets, roads, and prominent landmarks):



- Approximate property size:

Lot size (in feet) Frontage 50
Depth 175
or approx. acreage 0.20

- Condition: (check one)

a. Excellent ☐ b. Good ☒ c. Fair ☐
d. Deteriorated ☐ e. No longer in existence ☐

- Is the feature a. Altered? ☐ b. Unaltered? ☒

- Surroundings: (Check more than one if necessary)

a. Open land ☐ b. Scattered buildings ☐
c. Densely built-up ☒ d. Residential ☒
e. Commercial ☒ f. Industrial ☐
g. Other ☐

- Threats to site:

a. None known ☒ b. Private development ☐
c. Zoning ☐ d. Public Works project ☐
e. Vandalism ☐ f. Other ☐

- Date(s) of enclosed photograph(s): May, 1978

NOTE: The following (Items 14-19) are for structures only.

14. Primary exterior building material: a. Stone ☐ b. Brick ☒ c. Stucco ☐ d. Adobe ☐ e. Wood ☐
f. Other ☐
15. Is the structure: a. On its original site? ☒ b. Moved? ☐ c. Unknown? ☐
16. Year of initial construction 1928 This date is: a. Factual ☐ b. Estimated ☒
17. Architect (if known): Unknown
18. Builder (if known): Unknown
19. Related features: a. Barn ☐ b. Carriage house ☐ c. Outhouse ☐ d. Shed(s) ☐ e. Formal garden(s) ☐
f. Windmill ☐ g. Watertower/tankhouse ☐ h. Other ☐ i. None ☒

SIGNIFICANCE

20. Briefly state historical and/or architectural importance (include dates, events, and persons associated with the site when known):

As part of the Cathedral complex, this building - though the least successful of the 3 buildings architecturally, fits into the complex very well, through its use of brick and subdued detailing it forms a good foil to the other two buildings. Important due to its place as part of the major Catholic Cathedral in the city and its identity with this religion and its people who have been very important to the community since its inception.

21. Main theme of the historic resource: (Check only one): a. Architecture ☐ b. Arts & Leisure ☐
c. Economic/Industrial ☐ d. Exploration/Settlement ☐ e. Government ☐ f. Military ☐
g. Religion ☒ h. Social/Education ☐

22. Sources: List books, documents, surveys, personal interviews, and their dates:

Assessor's office

23. Date form prepared: 6/78 By (name): William E. Patnaude
Address: 1050 "S" St. City: Fresno, CA ZIP: 93721
Phone: (209) 486-8150 Organization: Allen Y. Lew & William E. Patnaude, Inc.

(State Use Only)



13-407

A-1

B-1

C-1,2

FH/Reeking C. Plan

C-P

EXHIBIT C:

NOT TO SCALE For Example Only




NOT TO SCALE For Example Only



NOT TO SCALE For Example Only



NOT TO SCALE For Example Only



NOT TO SCALE For Example Only



NOT TO SCALE For Example Only



Diagrams are not to Scale
Only for reference to Design

Curved 3/4
Pickets

Curved Pickets
With Press
Point Ends



7 feet

7 Feet
Tall
Fence

18.5"

Panels to be approx 10 Ft sections

Cast Iron
Caps

1 1/2" x 1 1/2"

4" Spacing



3/4 x 3/4 Pickets








3' x 3" Posts


10"

3 - 4" Spacing

Buried approx 24" in Cement







CANTILEVER GATE HARDWARE OFFERS A TROUBLE FREE AND EASY TO INSTALL SOLUTION FOR SLIDING GATES!

Our heavy duty system can handle almost all sliding gate applications. Sealed bearings and covered rollers avoid many of the usual maintenance and efficiency problems due to weather elements. They also help comply with UL325 and ASTM F2200 gate safety standards.



The technical innovation in the system, as compared to a *traditional sliding gate*, lies in the fact that the entire gate is cantilevered off the ground without any rollers traveling on the ground. This allows for free movement of the gate in uneven ground conditions and reduces the wear and tear on the gate and on any installed gate automation. The sealed bearings on the carriage assembly require no maintenance or lubrication. Besides, it gives the gate a nice clean look with minimal visible hardware. This engineered solution also reduces the length of the counterbalance resulting in a smaller overall gate length.



BENEFITS

- ▶ Higher weight capacity
- ▶ Works with any gate material
- ▶ Smaller overall gate length
- ▶ Reduces load on gate operator
- ▶ Low maintenance
- ▶ Minimal visible hardware
- ▶ Cost effective compared to traditional cantilever hardware
- ▶ Easy to install
- ▶ Durable even for high traffic applications

No Track or Grooves cut into Cement or Asphalt.
Eliminates the possibility of Trip and falls or Wheel chairs getting caught in grooves or channels.
Recommended wherever public access is expected.
Avoid potential lawsuits.



Monday Cathedral is open 7:00 am - 1:00 pm

Tuesday Cathedral is open 7:00 am - 8:00 pm

Wed Cathedral is open 7:00 am - 1:00 pm

Thursday Cathedral is open 7:00 am - 1:00 pm & 4:00 pm
7:00 pm

Friday Cathedral is open 7:00 am - 1:00 pm & 4:00 pm 7:30
pm

Sat Cathedral is open 8:00 am - 8:00 pm

Sun Cathedral is open 7:00 am - 7:00 pm

Arsonist strikes at St. John's Cathedral in downtown Fresno

Investigators were sent to St. John's Cathedral in downtown Fresno early Friday after an arsonist poured a flammable substance, possibly gasoline, at the front doors of the historic structure.

The doors of the building at Tulare and R streets were blocked for a time as the incident was investigated, briefly interfering with a funeral.

Fresno Fire Investigator Lee Wilding said there was another report of an arson in dumpsters nearby on Calaveras Street on Friday morning, but it was not known if the incidents were related. Wilding said earlier reports of an arson attempt near the Fresno Police Department on M Street and Mariposa Mall and at a church in Fresno's Chinatown turned out to be unfounded.

Read more here: <https://www.fresnobee.com/latest-news/article211418904.html#storylink=cpy>

**LATEST NEWS**

Arsonist strikes at St. John's Cathedral in downtown Fresno

BY JIM GUY*jguy@fresnobee.com*

May 18, 2018 09:13 AM

Updated May 18, 2018 02:42 PM

Investigators were sent to St. John's Cathedral in downtown Fresno early Friday after an arsonist poured a flammable substance, possibly gasoline, at the front doors of the historic structure.

The doors of the building at Tulare and R streets were blocked for a time as the incident was

Investigated, briefly interfering with a funeral.

By continuing to use this site, you give your consent to our use of cookies for analytics, personalization and ads. [Read](#)


Fresno Fire Investigator Lee Wilding said there was another report of an arson in dumpsters nearby on Calaveras Street on Friday morning, but it was not known if the incidents were related. Wilding said earlier reports of an arson attempt near the Fresno Police Department on M Street and Mariposa Mall and at a church in Fresno's Chinatown turned out to be unfounded.

Video surveillance recovered from cameras in front of St. John's show the suspect pouring a substance at the front of the church and igniting it. His first attempt to start a fire failed, but the second effort resulted in a large flash of fire that may have caused burns to the suspect, said Teresa Dominguez, a spokeswoman for the Diocese of Fresno.

Be the first to know.

No one covers what is happening in our community better than we do. And with a digital subscription, you'll never miss a local story.

SIGN ME UP!



By continuing to use this site, you give your consent to our use of cookies for analytics, personalization and ads. [Read](#)
Arson at Saint Johns cathedral

By Jim Guy

Dominguez said it was unclear why the suspect would want to damage the cathedral, but said the church wanted to reach out to him.

While making sure he is held accountable, she said it was important "to see what is going on in his life that would cause him to create (this) act of violence."

Anyone with information about the arson suspect is asked to call Crime Stoppers at 559-498-7867.


RELATED STORIES FROM FRESNO BEE



Diocese responds to arson at St John's Cathedral



By continuing to use this site, you give your consent to our use of cookies for analytics, personalization and ads. [Read](#)



An arsonist poured gasoline on the front doors of St. John's Cathedral early Friday, May 18, 2018 in downtown Fresno, California. Jim Guy - jguy@fresnobee.com

SUGGESTED FOR YOU




Barbara Bush Marries Craig Coyne in Maine Wedding



Ford Friend Told FBI She Was Pressured Into Altering Statement

By continuing to use this site, you give your consent to our use of cookies for analytics, personalization and ads. [Read](#)

M a r i p o s a S t



T u l a r e S t r e e t

'R' S t r e e t

----- Proposed 7ft fence

----- Existing fence
(to be replaced)

~~~~~ new Cantilever sliding Gate:~ powered- (P)  
no power (NP)  
Δ post



[illegible]

[illegible]



| Oct 11/2018                                                                                                                                                                                      |            | Created BY: Denise McKenzie -Risk Manager                                 |                        |  |                     |           |                    |  |  |  |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|---------------------------------------------------------------------------|------------------------|--|---------------------|-----------|--------------------|--|--|--|
| Vandalism/ Property Damage                                                                                                                                                                       | 2010- 2018 |                                                                           |                        |  |                     |           |                    |  |  |  |
| St John's Cathedral- The Cathedral for The Roman Catholic Bishop of Fresno                                                                                                                       |            |                                                                           |                        |  |                     |           |                    |  |  |  |
| 2814 Mariposa St                                                                                                                                                                                 |            |                                                                           |                        |  |                     |           |                    |  |  |  |
| Fresno, CA. 93721                                                                                                                                                                                |            |                                                                           |                        |  |                     |           |                    |  |  |  |
| <b>The Cathedral is the seat of the Catholic Church for the Diocese of Fresno.</b>                                                                                                               |            |                                                                           |                        |  |                     |           |                    |  |  |  |
| <b>The Diocese services over 2/Million Catholics in Fresno and the surrounding counties.</b>                                                                                                     |            |                                                                           |                        |  |                     |           |                    |  |  |  |
| <b>Vandalism/ Property Damages are a #1 concern in frequency along with parishioneer and employee safety.</b>                                                                                    |            |                                                                           |                        |  |                     |           |                    |  |  |  |
| <b>** St John's Cathedral is in the top two of property damage frequency due to vandalism/theft and hate crime activity.</b>                                                                     |            |                                                                           |                        |  |                     |           |                    |  |  |  |
|                                                                                                                                                                                                  |            |                                                                           |                        |  |                     |           |                    |  |  |  |
|                                                                                                                                                                                                  |            |                                                                           |                        |  |                     |           |                    |  |  |  |
| DATE                                                                                                                                                                                             |            | DESCRIBE                                                                  | AMOUNT PAID IN DAMAGES |  |                     | PHOTO/INV |                    |  |  |  |
| 5/9/2010                                                                                                                                                                                         |            | Female threw rock<br>into stained glass<br>window of church               |                        |  | \$ 1,750.00         |           | INV Only           |  |  |  |
| 9/20/2011                                                                                                                                                                                        |            | Vandalism(Copper wire) A/C Units                                          |                        |  | \$ 4,500.00         |           | INV Only           |  |  |  |
| 7/9/2012                                                                                                                                                                                         |            | Vandalism(Copper wire) A/C Units                                          |                        |  | \$ 11,591.00        |           | INV Only           |  |  |  |
| 10/29/2013                                                                                                                                                                                       |            | Brk-In Vandalism                                                          |                        |  | Donation- CVR       |           | Fresno Bee         |  |  |  |
| 1/22/2014                                                                                                                                                                                        |            | Vandalism(Copper wire) A/C Units                                          |                        |  | \$3,605.41          |           | INV Only           |  |  |  |
| 5/19/2014                                                                                                                                                                                        |            | Vandalism(Copper wire) A/C Units                                          |                        |  | \$ 4,658.00         |           | INV & Many Photo's |  |  |  |
| 6/5/2015                                                                                                                                                                                         |            | Vandalism Broken Window of Church                                         |                        |  | \$ 2,145.00         |           | INV & Photo's      |  |  |  |
| 6/2/2016                                                                                                                                                                                         |            | Vandalism Stained Glass/Rectory                                           |                        |  | \$ 900.00           |           | Inv Only           |  |  |  |
| 12/7/2017                                                                                                                                                                                        |            | Brk-In Vandelim/Theft- Church/Criminal TRO                                |                        |  | \$ 21,207.24        |           | Photo/INV          |  |  |  |
| 8/27/2017                                                                                                                                                                                        |            | Rock-Brkn Window Church Basement                                          |                        |  | \$ 750.00           |           | Photo/Inv          |  |  |  |
| 1/9/2018                                                                                                                                                                                         |            | Vandalism/<br>Statue/OurLady & Child/<br>Criminal TRO (Child<br>Molestor) |                        |  | \$ 7,139.01         |           | Photo/INV          |  |  |  |
|                                                                                                                                                                                                  |            | <b>Total Property Damages ONLY</b>                                        |                        |  | <b>\$ 58,245.66</b> |           |                    |  |  |  |
| <b>** This total DOES NOT INCLUDE Legal Fees paid to attorneys for Criminal (TRO- Temporary Restraining Orders) or for ONSITE Security that now is ongoing and in excess of over \$70,000.00</b> |            |                                                                           |                        |  |                     |           |                    |  |  |  |

|                                                                                                                                                                                                  |  |                                                                           |                        |  |               |           |                    |  |  |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|---------------------------------------------------------------------------|------------------------|--|---------------|-----------|--------------------|--|--|
| Oct 11/2018                                                                                                                                                                                      |  | Created BY: Denise McKenzie -Risk Manager                                 |                        |  |               |           |                    |  |  |
| Vandalism/ Property Damage 2010- 2018                                                                                                                                                            |  |                                                                           |                        |  |               |           |                    |  |  |
| St John's Cathedral- The Cathedral for The Roman Catholic Bishop of Fresno                                                                                                                       |  |                                                                           |                        |  |               |           |                    |  |  |
| 2814 Mariposa St                                                                                                                                                                                 |  |                                                                           |                        |  |               |           |                    |  |  |
| Fresno, CA. 93721                                                                                                                                                                                |  |                                                                           |                        |  |               |           |                    |  |  |
| The Cathedral is the seat of the Catholic Church for the Diocese of Fresno.                                                                                                                      |  |                                                                           |                        |  |               |           |                    |  |  |
| The Diocese services over 2/Million Catholics in Fresno and the surrounding counties.                                                                                                            |  |                                                                           |                        |  |               |           |                    |  |  |
| Vandalism/ Property Damages are a #1 concern in frequency along with parishioneer and employee safety.                                                                                           |  |                                                                           |                        |  |               |           |                    |  |  |
| ** St John's Cathedral is in the top two of property damage frequency due to vandalism/theft and hate crime activity.                                                                            |  |                                                                           |                        |  |               |           |                    |  |  |
| DATE                                                                                                                                                                                             |  | DESCRIBE                                                                  | AMOUNT PAID IN DAMAGES |  |               | PHOTO/INV |                    |  |  |
| 5/9/2010                                                                                                                                                                                         |  | Female threw rock<br>into stained glass<br>window of church               |                        |  | \$ 1,750.00   |           | INV Only           |  |  |
| 9/20/2011                                                                                                                                                                                        |  | Vandalism(Copper wire) A/C Units                                          |                        |  | \$ 4,500.00   |           | INV Only           |  |  |
| 7/9/2012                                                                                                                                                                                         |  | Vandalism(Copper wire) A/C Units                                          |                        |  | \$ 11,591.00  |           | INV Only           |  |  |
| 10/29/2013                                                                                                                                                                                       |  | Brk-In Vandalism                                                          |                        |  | Donation- CVR |           | Fresno Bee         |  |  |
| 1/22/2014                                                                                                                                                                                        |  | Vandalism(Copper wire) A/C Units                                          |                        |  | \$3,605.41    |           | INV Only           |  |  |
| 5/19/2014                                                                                                                                                                                        |  | Vandalism(Copper wire) A/C Units                                          |                        |  | \$ 4,658.00   |           | INV & Many Photo's |  |  |
| 6/5/2015                                                                                                                                                                                         |  | Vandalism Broken Window of Church                                         |                        |  | \$ 2,145.00   |           | INV & Photo's      |  |  |
| 6/2/2016                                                                                                                                                                                         |  | Vandalism Stained Glass/Rectory                                           |                        |  | \$ 900.00     |           | Inv Only           |  |  |
| 12/7/2017                                                                                                                                                                                        |  | Brk-In Vandelim/Theft- Church/Criminal TRO                                |                        |  | \$ 21,207.24  |           | Photo/INV          |  |  |
| 8/27/2017                                                                                                                                                                                        |  | Rock-Brkn Window Church Basement                                          |                        |  | \$ 750.00     |           | Photo/Inv          |  |  |
| 1/9/2018                                                                                                                                                                                         |  | Vandalism/<br>Statue/OurLady & Child/<br>Criminal TRO (Child<br>Molestor) |                        |  | \$ 7,139.01   |           | Photo/INV          |  |  |
| Total Property Damages ONLY                                                                                                                                                                      |  |                                                                           |                        |  | \$ 58,245.66  |           |                    |  |  |
| <b>** This total DOES NOT INCLUDE Legal Fees paid to attorneys for Criminal (TRO- Temporary Restraining Orders) or for ONSITE Security that now is ongoing and in excess of over \$70,000.00</b> |  |                                                                           |                        |  |               |           |                    |  |  |



## Vandalism limits public access at St. John's Cathedral

10/29/2013

over

0:00

Crooks are forcing local churches to change the way they operate. The latest victims are parishioners at St. John's Cathedral in downtown Fresno.

Share G+ Tweet

October 29, 2013 12:00:00 AM PDT

By Rick Montanez

FRESNO, Calif. -- Crooks are forcing local churches to change the way they operate. The latest victims are parishioners at St. John's Cathedral in downtown Fresno.

The closure is brand new this week after a man kicked down a 110-year-old door inside the cathedral. Valley Catholics are outraged by the crime, especially since the man was caught on camera walking into a sacred room.

Security cameras caught a man repeatedly kicking at the door to the sacristy inside St. John's Cathedral on October 23. In the video, the man pauses after a few attempts then



Diocese of Fresno. "And when you're violated in that way, it's heartbreaking. It's heartbreaking for all of us."

The damage to the 110-year-old door is on the inside of the sacristy where our camera wasn't allowed. Neither was the man in the video but you can clearly see him ignoring the ropes that close off the altar to the public. Several times during his hour and half stay the camera catches a good look at his face.

"This is happened more and more, there's just no respect for anything anymore," McKenzie said. "Our churches are suffering all up and down the diocese."

Now, instead of open doors, a sign says the church is closed because of disrespect to the sanctuary. Churches all over the valley are feeling a similar impact caused by vandalism. At St. James Anglican Cathedral in central Fresno people have to ask to be let in to pray for security reasons.

Thousands of dollars have been spent on repairs, like when crooks tried to steal this giant church bell.

"Churches are like anybody else," said Father Carlos Raines. "We've had our air conditions stolen, businesses around have had theirs stolen. We're all suffering at a time when a lot of people are suffering."

"Not only is it defacing things that are very close to our hearts," McKenzie said. "It's something that's a burden financially for the parishes and also for the diocese."

St. John's will still keep its regular service hours. The church will open 30 minutes before mass and close 30 minutes after. It will be open during special occasions.



---

[Home](#)

---

[AccuWeather](#)


---

[Traffic](#)

---

[Local News](#)



















5/19/14











6-5-2015  
damage +  
repair  
complete
























12/7/2017







8/27/2017













8/27/2017

